

MATERIAL SAFETY DATA SHEET  
ABR+1 MOLD & MILDEW REMOVER

---

**SECTION I - PRODUCT IDENTIFICATION**

Manufacturer's Name: American Building Restoration Products, Inc.

9720 S. 60th St.  
Franklin, Wisconsin 53132

Emergency Phone No: Chemtrec 1-800-424-9300

Product Trade Name: ABR+1 Mold & Mildew Remover

**DOT Proper Shipping Name:** Liquid Oxalic Acid N.O.S.

---

**SECTION II - HAZARDOUS INGREDIENTS**

	CAS NO.	AMT(%)	OSHA PEL	ACGIH TLV
Oxalic Acid	144-62-7	<10	TWA 1mg/m3	TWA 1mg/m3 STEL 2 mg/m3

---

**SECTION III - PHYSICAL DATA**

Boiling Range: Above 212°F  
Vapor Density: Heavier than air  
Evaporation Rate: Slower Than Ether  
Percent Volatile By Volume: 86%

---

**SECTION IV - HEALTH HAZARD DATA**

**Threshold Limit Value: See Section II**

Effects of Over Exposure:

Eyes contact: Can cause irritation

Skin contact: Can cause irritation

Ingestion: Results in severe damage to tissue and mucous membranes

**EMERGENCY AND FIRST AID PROCEDURES:**

**EYES:** Flush thoroughly for 15 minutes with water. See Physician if irritation persists.

**SKIN:** Wash thoroughly with water. Remove contaminated clothing and launder before reuse.

MATERIAL SAFETY DATA SHEET  
ABR+1 MOLD & MILDEW REMOVER

INGESTION: Give two (2) glasses of milk. Call Physician immediately.

---

**SECTION V - REACTIVITY DATA**

Stability: Stable

Hazardous Polymerization: Will Not occur.

Hazardous Decomposition Products: May form toxic materials as carbon dioxide, carbon monoxide, acid fumes, etc..

Conditions to Avoid: Strong Alkalis

Incompatibility: (materials to avoid): Contact with strong alkalis -e.g., NAOH, NH<sub>4</sub>OH, and bleaching materials.

---

**SECTION VI - SPILL OR LEAK PROCEDURES**

Steps to be taken in case material is released or spilled: Cover with

soda ash or sodium bicarbonate. Mix and scoop into container for proper disposal.

WASTE DISPOSAL METHOD: Contact local municipal, state, or federal agencies to ensure compliance of disposal method with current regulations.

NOTE: Empty containers can have residues, gases or mists and are subject to proper waste disposal.

---

**SECTION VII - SPECIAL PROTECTION INFORMATION**

VENTILATION: Use adequate ventilation

PROTECTIVE GLOVES: Rubber gloves

EYE PROTECTION: Splash proof chemical goggles.

PROTECTIVE CLOTHING OR EQUIPMENT: Wear full protective clothing.

---

**SECTION VIII - SPECIAL PRECAUTIONS**

Precautions to be taken in handling and storing: Store in a cool, dry place. Store away from oxidizers.

Other Precautions: Do not allow to freeze.

---

MATERIAL SAFETY DATA SHEET  
ABR+1 MOLD & MILDEW REMOVER

**SECTION IX - PREPARATION DATE OF MSDS**

Occupational Health & Safety Dept.  
12/16/93

Date:

5/03/92 \_\_\_\_\_

Supersedes:

**DISCLAIMER:**

The information contained herein is based on the data available to us and is believed to be correct. However, American Building Restoration Products, Inc. makes no warranty, express or implied regarding the accuracy of this data or the results to be obtained from the use thereof.

American Building Restoration Products, Inc. assumes no responsibility for injury from the use of the product described herein.

\_\_\_\_\_  
ABR+1